

NEW PRODUCT BULLETIN

Water Pump Timing Belt Replacement Kits

AISIN kit includes the following components:

- AISIN Water Pump w/ Gasket
- Mitsuboshi Timing Belt
- Mitsuboshi Balance Shaft Belt
- KOYO Tensioner Bearing
- NSK Balance Shaft Tensioner Bearing
- Genuine Honda Tensioner Spring
- Genuine Honda Balance Shaft Tensioner Spring



**PART NUMBER:
TKH-006**

OEM Part Number Reference:

WATER PUMP W/GASKET: 19200-P0A-003

TIMING BELT: 14400-PAA-A02

BALANCE SHAFT BELT: 13405-PT0-004

TENSIONER SPRING: 14516-P0A-000

BALANCE SHAFT TENSIONER SPRING: 13407-P0A-000

TENSIONER BRG: 14510-PT0-004

BALANCE SHAFT TENSIONER BEARING: 13404-PT0-004

MAKE	MODEL	YEAR	ENGINE	CYL	LITER
ACURA	CL	1998-1999	F23A1	L4	2.3L
HONDA	ACCORD DX/EX/LX/SE	1998-2002	F23A	L4	2.3L
	ODYSSEY	1998	F23A	L4	2.3L
	ACCORD EX/W-V-TEC	1994-1997	F22B	L4	2.3L

