


## Supersede Announcement

## **ENGINE WATER PUMP**

## **Effective: IMMEDIATELY**

WPZ-043 is superseded to WPZ-701.



Until your inventory is depleted, you may use WPZ-043 in Applications calling for WPZ-701.

## **Interchanges:**

| 1F20-15-010  |         |
|--------------|---------|
| 1F70-15-010  |         |
| 1F70-15-100  |         |
| L327-15-100  |         |
| L327-15-100A | Mazda   |
| LF01-15-100  | iviazua |
| LF52-15-100  |         |
| LF52-15-100A |         |
| LF94-15-100  |         |
| LF94-15-100A |         |

| LF94-15-100A |            |
|--------------|------------|
| 4S4Z-8501-AA | Ford       |
| 4S4G-8501-BD |            |
| LR025302     |            |
| LR040990     | Land Rover |
| LR053310     |            |
| 31370908     | Volvo      |
| 31480425     | V 01V0     |



For additional details and application information, please review the data provided by AISIN, or your catalog provider, or visit us on our website: www.aisinaftermarket.com Please contact your AISIN sales representative for additional information.

Distributed by